



ANTI-ENTRAPMENT DEBRIS DRAIN

CERTIFICATE OF CONFORMITY

1. PRODUCT: MDX2 ANTI-ENTRAPMENT

DEBRIS DRAIN

XXX-202-2210-XX CONCRETE
XXX-212-2210-XX VINYL
XXX-222-2210-XX ONE-PIECE LOW
FIBERGLASS
XXX-202-2221-XX RETRO
CONCRETE VINYL FIBER

-XX DESIGNATES COLOR

The MDX2 Anti-Entrapment Debris Drain is a 13"-16" rectangular drain fitting. It includes a sump and 2 1/2" pipe with a rectangular raised cover that is affixed to a concrete leveling ring or directly to the sump. The drain has two straight openings at opposite ends to accept large debris.

2. APPLICABLE STANDARD OR REGULATION:

VGB Pool and Spa Safety Act 2008

ASME A112.19.8-2008a

ANSI/APSP-7 2006

3. DOMESTIC MANUFACTURER:

Paramount Leisure Industries

DBA/ Paramount Pool and Spa Systems

295 E Corporate Place #100

Chandler, AZ 85225

480-893-7607

800-621-5886

4. US IMPORTER: N/A

5. PRIVATE LABELER: N/A

6. Test Record Documentation:

Dominic Conn

Director of Engineering

Paramount Pool and Spa Systems

Chandler, AZ 85225

dconn@1paramount.com

480-893-7607 x250

Kris Adilukito P.E.

IAPMO R&T

Manager Testing and QA

5001 East Philadelphia Street

Ontario, CA 91761

kris.adilukito@iapmortl.org

909-472-4124

7. Date and Place of Manufacture:

November 2008

Chandler, AZ

8. Date and Location of Test Report:

April 18, 2011

IAPMO R&T Lab

9. Name of Third Party laboratory:

IAPMO R&T Lab

5001 East Philadelphia Street

Ontario, CA 91761-2816 USA

Install Date _____

Replacement 5 years from installed date _____